



CLOCK SPRING®

Pipe Support

The Fast, Economical Solution for Low Pressure Pipeline Repair



3 x 18" repairs were made in support locations.

The Pipe could not be raised so blocks were inserted and the supports were cut away. The pipe was then hand prepared to remove all traces of zinc paint and any corrosion scabs.

The 3 repairs were completed within 2 hours.



FOR FURTHER INFORMATION ON CLOCK SPRING® REPAIR SOLUTIONS CONTACT:

**Clock Spring Company, L.P.
14107 Interdrive West, Houston, TX 77032
Telephone: 281-590-8491 • Facsimile: 281-590-9528
Email: sales@clockspring.com**