



# CLOCK SPRING®

## BURST TEST RESULTS

### BURST TEST ON UNREPAIRED SPOOL



Defect Length = 7 in, Defect Width = 3 in, Depth = 80% Wall Loss

**Defect Burst at 1015 psi**

### BURST TEST WITH CLOCK SPRING REPAIR





Clock Spring Repair Made on Same Size Defect

**The Pipe Burst at 2900 psi!**



# CLOCK SPRING®

## BURST TEST CUTAWAY



**FOR FURTHER INFORMATION ON CLOCK SPRING® REPAIR SOLUTIONS CONTACT:**

**Clock Spring Company, L.P.**

**14107 Interdrive West, Houston, TX 77032**

**Telephone: 281-590-8491 • Facsimile: 281-590-9528**

**Email: [sales@clockspring.com](mailto:sales@clockspring.com)**